

Bethel Creek RRS Sites and Contaminants

<i>Site(s):</i>		<i>Contaminant(s):</i>
SS-01	POL Facility	POL
SS-02	Vehicle Maintenance Building	Drums Debris Hazardous Materials POL Solvents
SS-03	Antenna Building 1126	Antifreeze POL
SS-04	Equipment Building 1052	POL
SS-05	North End of Equipment Building	POL
SS-06	East Road Contaminated Soil	DDT
LF-07	Solid Waste Landfill	Hazardous Materials Paint POL Solvents
OT-08	Themopiles, Permafrost, and Conductors	Antifreeze POL
SS-09	Contaminated Soil Various Locations	POL
SS-10	White Alice Site	Asbestos PCB
OT-11	Barrel Storage	PCB POL
SS-13	Bethel BIA, 27 Acre Site	DDT PCB POL